proved For Release Space for Permanent Agency Records 25X1A6d Center Operations

25X1A6d

it is our opinion that the area could be made suitable for permanent records center operations only with expenditures in excess of \$100,000. It was agreed by all officials concurring in the Records Center Review Submittal that it would be preferable to build rather than to spend at approximately the same amount which is 25X1A6d equivalent to about 25% of the cost of construction.

2. The GSA estimate for converting the for use 25X1A6d as a permanent records center is \$95,800. This estimate on the cost for converting is based on the fact that the structure appears 25X1A6d to be equivalent to the with respect to the kind and 25X1A6d extent of alterations needed. Following is the GSA estimate for convert-

25X1A6d ing the

Partitions 3,500,00 Asphalt tile 1,500.00 Interior painting 5,000.00 New toilets 9,000,00 Masonry 3,500.00 Ventilation 2,000**.00** Air-Conditioning 6,000,00 Heating 2,500.00 Lighting and fixtures 54,000.00 v Fire alarm 3,000.00 Fence 4,000.00 Engineering Fee .800.00 Total cost of job 95,800,00

It would appear that the alteration cost for would be in25X1A6d excess of this amount because of the necessity for installing a false ceiling in order to obtain proper heating. In lowering the ceiling Sanitized - Approved For Release: CIA-RDP70-00211R000100210048-4 it would also be necessary to install an additional sprinkler system.

## Sanitized - Approved For Release -RDP70-00211R000100210048-4

should it be decided to use the space there still may be 25X1A6d a problem in connection with future expansion. This would occur because the surrounding space will have been assigned by GSA, which would not be able to make it available to the Agency when needed because of other committments.

3. We presume that the Security Office will submit their requirements with respect to the guard posts. However, one post will be required and probably two. This represents a continuing cost of \$21,000 for each 24 hour post which would not be incurred if new construction was approved, because the present guard force 25X1A6d is considered adequate.

25X1A6d